

FIG. 1




FIG. 2

FIG. 3




FIG. 5






FIG. 4




F16 6

502

504



Artifact Produced From Full Rate Modem Simulation with Rate Step-down Error Recovery:



Artifact Produced From Full Rate Modem Simulation with Woods Filter Clamp